Qty:

1 Um:

Each

: FWD X-TUBE

. D2889 REV B

: D2889

: N/A

: 4/4/2008

: B

Date:

Monday, 3/17/2008 11:57:13 AM

Process Sheet

Drawing Name

Part Number

Drawing Number

Project Number

Drawing Revision

Customer

Job Number

: CU-DAR001 Dart Helicopters Services : 38038

Estimate Number

: 10006

P.O. Number

: 3/17/2008 This Issue

: NC

Prsht Rev. First Issue : //

Previous Run

: 38037

Written By Checked & Approved By

Comment

: Est Rev:A

S.O. No. :

: LANDING GEAR

Material Due Date

New Issue 05-10-25 JLM

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description: Crosstube material

D6005180

Comment: Qty.:

Crosstube material

1.0000 Each(s)/Unit

Total:

1.0000 Each(s)

Pick:

BENDING

1 D2889

Qty Part number

Description

Batch

Fwd Crosstube

BENDING MACHINE



Comment: LANDING GEAR RESOURCE 1

1-Bend D2889 as per Dwg D2889 and Folio FT001

LANDING GEAR RESOURCE

LANDING GEAR 1

Comment: LANDING GEAR RESOURCE 1

1-Deburr and Polish

4.0

3.0

QC15

Comment: DIMENSIONAL CHECK OF X-TUBES

5.0

HAND FINISHING1

HAND FINISHING RESOURCE #1

DIMENSIONAL CHECK OF X-TUBES



Comment: HAND FINISHING RESOURCE #1

Acid etch and alodine as per QSI 005 4.1

Inside and outside of tube





Page 1

Dart Aerospace Ltd

DuitAo	·oopaoc				4				
W/O:			WC	ORK ORDER CHANG	ES				
DATE STEP		PROCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date:	
					QA: N	I/C Close	d:	Date: _	
NCR:		,	WORK ORD	ER NON-CONFORMA	NCE (NCF	₹)			
	STEP	Description of NC Section A	Corrective Action Section			Verification		Approval	Approval
DATE			Initial Chief Eng	Action Description Chief Eng	Sign 8 Date			Chief Eng	QC Inspector

NOTE: Date & initial all entries

Date: Monday, 3/17/2008 11:57:13 AM Kim Johnston User: **Process Sheet** Drawing Name: FWD X-TUBE Customer: CU-DAR001 Dart Helicopters Services Job Number: 38038 Part Number: D2889 Job Number: Description: Seq. #: **Machine Or Operation:** INSPECT POWDER COAT/CHEN 6.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION PACKAGING RESOURCE 1000104 D 111111111 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: W/O 37943 8.0 08/04/08/ Comment: FINAL INSPECTION/W/O RELEASE Job Completion N 08-4-04

Dart Aerospace Ltd


W/O:		WORK ORDER CHA	ANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
	:						
		•					
Part No	:	PAR #: Fault Category:	NCR: Yes	No DQ	A:	Date: _	
			QA:	N/C Close	d:	Date:	
NCR:		WORK ORDER NON-CONFO	WORK ORDER NON-CONFORMANCE (NCR)				

NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
	STEP	Description of NC		Corrective Action Section B		Verification	Ammrough	Ammassal	
DATE		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		Approval Chief Eng	Approval QC inspector	
•									

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	38038
Description: Crosstube Fwd	Part Number:	D2889
Inspection Dwg: D2889 Rev: B		Page 1 of 1

Required Dimension	Min	Max
Height	49.875	50.125
1/2 Span	69.275	69.525
Angle	49 ,	52
Total Span	138.55	139.05



Rev	Date	Change	Revised by	Apprøved
Α	07.02.06	New Issue	KJ/JM KJ/	/pm
·			. ()	

